





Växthushylla

Manual










Shelving

Please drill two holes at same height on each corner post before glazing.



Staging

Please drill two holes at same height on each corner post before glazing.



PACKING LIST



Model 134			
Part Name	Part No.	Length	Qty
Slat	900	1210	3
Slat Shelving Horizontal	906	325	3
Small Diagonal Support	907	395	3
M6x10 Bolt			12
M6 Nut			18
M6x10 Crop - head Bolt			6
Model 136			
Part Name	Part No.	Length	Qty
Slat	901	1820	3
Slat Shelving Horizontal	906	325	4
Small Diagonal Support	907	395	4
M6x10 Bolt			16
M6 Nut			24
M6x10 Crop - head Bolt			8